HDPE Weave Maintenance

Clean the HDPE Weave with mild soap and water, hose to rinse.